Description	Est. Annual Hours			Southeast			Sou	theast Pump
		Flygt 73%	Mader 16%	Pump 11%	Xylem 73%	Mader 16%		11%
Pump Repair - Shop Labor During Business Hours	10,000	7300	1600	1100	\$ 620,500.00	\$ 80,000.00	\$	60,500.00
Pump Repair - Field Labor During Business Hours	7,500	5475	1200	825	\$ 547,500.00	\$ 72,000.00	\$	45,375.00
Pump Repair - Emergency Shop Labor	5,000	3650	800	550	\$ 465,375.00	\$ 56,000.00	\$	45,375.00
Pump Repair - Emergency Field Labor	5,000	3650	800	550	\$ 547,500.00	\$ 64,000.00	\$	45,375.00
Pump Inspection Fee Labor (if repair not performed)	5,000	3650	800	550	\$ -	\$ -	\$	30,250.00
Crane Services Hourly Fee	25,000	18250	4000	2750	\$ -	\$ 600,000.00	\$	693,000.00
Description	Est. Annual Usage	1						
Group B. NEW PUMPS/ PARTS - All Inclusive Cost								
New Pumps	\$ 1,500,000.00	\$ 1,095,000.00	\$ 240,000.00	\$ 165,000.00	\$ 104,025.00	\$ 24,000.00	\$	16,500.00
Parts	\$ 500,000.00	\$ 365,000.00	\$ 80,000.00	\$ 55,000.00	\$ 34,675.00	\$ 8,000.00	\$	5,500.00
Five (5								
		•						
BID SUMMARY		7						
BID SOMMAN		1						
Group A. PUMP REPAIRS Total Amount					\$ 2,180,875.00	\$ 872,000.00	\$	919,875.00

\$ 1,350,000.00

Unspecified Funds

**Grand Total Bid Submittal** 

Total Award \$ 28,540,750.00

985,500.00 \$ 216,000.00 \$

17,218,875.00 \$5,760,000.00 \$ 5,561,875.00

148,500.00

Vendor R.C. Beach & Assoc., Inc. bid only one line item, Group B New Pumps, and was the highest priced vendor for this line item. Additionally, R.C. Beach & Assoc., Inc. was deemed non-responsive due to inability to guarantee meeting delivery deadlines as defined in Section 7 & 8 of the bid specifications.