

Field Report

Application #: WND-22-00252

Address: 1605 Pass A Grille Way, St. Pete Beach

Date of Field Visit: 11/17/22

Time of Field Visit: 11:30

Tide: 2.0' below MHW

Tide Range: 2.3'

Correction for MLW: -0.3'

Shoreline: Seawall with riprap.

Vegetation: Caulerpa spp.

Notes/Comments: Existing dock walkout located 11' to 17' from right property line. Head ends 55' from right property line. Sister poles located @ 67'-68' from right property line.

Depths off of existing walkout (left side):

Distance	Depth	MLW Depth	Notes/Comments
Wall	1.2'	0.9'	On scattered riprap/rocks. Attached filamentous algae growing on riprap.
7'			Caulerpa begins on the right side of walkout.
8'			Approximate end of riprap.
10'	1.4'	1.1'	Firm sand bottom (continues).
20'	2.0'	1.7'	
30'	2.9'	2.6'	Approximate end of Caulerpa on right side.
40'	3.9'	3.6'	
50'	4.9'	4.6'	
55'			End of existing dock.